

	<b>NW9304 BAR CODE SPECIFICATION WORK INSTRUCTION</b>		
	REVISION DATE	LEVEL	PAGE NUMBER
	28-SEPT-09	N/C	Page 1 of 2
Validated By: Jo Ann Kurtz Date: 9/30/09		Approved by: Joyce Krieger Date: 9/30/09	

## 1.0 PURPOSE

- 1.1 To give Wesco Aircraft's suppliers, guidelines to provide bar code (labels) on the outer container of items shipped to Wesco Aircraft.

## 2.0 SCOPE

- 2.1 This procedure encompasses the requirements for Wesco Aircraft suppliers to follow when completing bar code labels for shipments.

## 3.0 REQUIREMENTS

- 3.1 The bar code font required is 3 of 9 (Codes 39) type, with human readable characters printed below each bar code.
- 3.2 Data Fields required but not limited to are:
- 3.2.1 Wesco Aircraft Purchase Order Number.
  - 3.2.2 Wesco Aircraft ordered part number.
  - 3.2.3 Quantity shipped.
  - 3.2.4 Manufacturers Lot Number.
  - 3.2.5 Number of boxes shipped (Note: This does not have to be bar coded but should be located with the above information).
  - 3.2.6 Optional: Weight of Boxes/Packages
- 3.3 Label Size and Location
- 3.3.1 Two bar codes are required. One on the outside of the container and an extra one inside with the documentation packet.
    - 3.3.1.1 The outer container label shall have the bar code printed on it. Reference sample on page 2.
- 3.4 Size of the bar code information shall be .375 inches minimum in height and must be placed as not to block any information. Reference sample on page 2

**UNCONTROLLED IF PRINTED**



NW9304 BAR CODE SPECIFICATION WORK INSTRUCTION

REVISION DATE

LEVEL

PAGE NUMBER

28-SEPT-09

N/C

Page 2 of 2

OPTIONAL →

WEIGHT, OF  
BOXES / PACKAGES  
12 LBS

TO:  
WESCO AIRCRAFT (661) 775-7200  
27727 AVENUE SCOTT  
VALENCIA, CA 91355

P.O. NUMBER



513595

PART NUMBER



300109-6-750

QUANTITY SHIPPED



500

LOT NUMBER



C001285A

NUMBER OF BOXES SHIPPED



1

OPTIONAL →

UNCONTROLLED IF PRINTED